DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT FOD 194 28831

Date of Maintenance 10/13/22 Rea	ason for Maintenance:			
Property Address: 19457 Orwell	Ave N Pro	perty Owner's Na	me: Dawn + Michael Zio	egelski
Municipality: Marine	State MN Zip Co	de 55047	GEO Code/Property I.D. #:	,
What was done to the system of		Dittements (m)	Hebasopolis Hemistonomin	
Tank(s) Pumped	Liquid Level of Ta	A		
Sludge and scum measured. Do tanks need to be pumped?	Liquid Level Of Te	In.	Sludge Level in. Scum Leve	el in.
Yes No (If no provide measure)	Total (Sludge + Se	tum) / [iquid Level = % Sludge & S	icum
1. Access used to remove septage: Main		(C- 4- 42 b-t)	* Tank must be pumped	
			ic aranta-shan arac	III TUIS VAIRE
2. If maintenance hole was used, were all co	vers securely replaced? -	Yes No ple	ase explain	
Explanation:				
3. If owner refuses to allow a Subsurface S them complete and sign the following s	ewage Treatment Syster latement:	n (SSTS) to be pu	mped through the maintenance h	ole, have
•			r & mar in	
hole. I understand that removal of solids a	nd liquids through other a	allow the remova	of solids and liquids through the ma	aintenance
4. Is the tank designed as a leaky tank? examp	ple: seepage pit, cesspool, di	vwell. leachina nit	COnsidered maintenance.	
Tank#1 Yes ANO Verificatio Meth				
	= V139a			
Tank#2 Yes No Verificatio Metho				
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretreat	ment or pump ta	nk below the operating depth or e	vidence of
Tank	Leaking Out	ers: Leaking In	Court	
Septic/Holding Tank #1	Yes No	Yes Divi	Cover Damage	
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No		
Pretreatment Tank	☐Yes ☐No	Yes No		
Pump Tank	☐ Yes ☐ No	Yes No	(2) 100	
. How many gallons of septage were remov	red?			
ank#1 1250 Tank#2	Pretreatment Tani	,	Dames Toul.	
			Pump Tank	
Other information: List any troubleshooti	ng, minor repairs conduc	ted, tank safety	concerns, or other concerns.	
Cortifications I haraby contificate a State of the	Manager 10 10 10 10 10 10 10 10 10 10 10 10 10			
Certification: I hereby certify as a State of N and made the observations, o	innesota certified SSTS Mi or directly supervised other	aintainer that I per is in the performa	sonally conducted the work	
Maintainer's Name: Olson's Sewer Service, Ir		2		
			yons Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintai	iner's Phone #: 651-464-2	082	(
Maintainer's Signature		Date:	intertan	
- 4	V		10/13/22	