

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety					
<u>prior</u> to performing maintenance activi	ties and remain on	-site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance: 5/4127 Reason	for Maintenance:	Routine			
Property Address: 11330 50†	St No	Property Owner's N	ame: Mus	Tenpas	
Municipality: <u>Layle Flyro</u> ZIP:	H2 Property Ide	ntification Number:		_	
Maintenance Permit No: 02065426031	Maintainer Name a	nd License No. Pink	y's Environmental Sev	ver Service/ L1673	
Maintenance Performed	Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank ——— in				
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)					
<ol> <li>Access used to remove septage:  Maintena</li> <li>Were all covers securely replaced? Yes</li> <li>Is there evidence of tank leakage from a sepevidence of damaged, cracked, or structure</li> </ol>	□ No ptic, holding, preti	reatment or pump	tank below the opera	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	✓ Yes ☐ No	Yes No	☐ Yes ☐ No		
Septic/Holding Tank #2	☑ Yes ☐ No	Yes No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed Tank #1 500 gal Tank #2 500 gal 5. Other information: List any troubleshooting	_gal Pretreatmen	nducted, tank safe	ty concerns, or other		
240,621	for				

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673