

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	for Maintenance: _		5- 18-00		
Property Address: 5535 Garden Dr Woodbury, N	<u>MN</u> F	roperty Owner's N	ame: Jim Docken		
Municipality: ZIP: _5512	9 Property Ider	ntification Number:			
Maintenance Permit No: N	Naintainer Name ar	d License No. Sch	lomka Service LLC	C/L2989	
			***************************************		
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
☑ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?			evel X 100 nks must be pumped		
$\square$ Yes $\square$ No (if no provide measurements)	= % Studge & Sci	Jiii Tai	iks must be pumped	II 23% OF greater	
1. Access used to remove septage:   Maintenar	oce Hole X Other (6	enter authorization co	nde)		
		incer addition action of	ode)		
2. Were all covers securely replaced?		estment of numb	tank balaw tha ana	rating donth or	
3. Is there evidence of tank leakage from a sep evidence of damaged, cracked, or structural	ally unsound main	tenance hole cove	rs? No - couldn't	conf <u>irm precast via</u>	
	2701			conf <u>irm precast via</u>	
			camera	conr <u>irm precast via</u>	
Tank	Leaking Out	Leaking In	camera  Cover Damage	confirm precast via	
Tank Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage  Yes No	conr <u>irm precase via</u>	
Septic/Holding Tank #1	Leaking Out  Yes No Some answers un	Leaking In  Yes No known. Pumped thro	Cover Damage  Yes No  ough inspection pipe.	conr <u>irm precase via</u>	
	Leaking Out	Leaking In  Yes No known. Pumped thro	Cover Damage  Yes No- pugh inspection pipe.  Yes No	conr <u>irm precase via</u>	
Septic/Holding Tank #1	Leaking Out  Yes No Some answers un	Leaking In  Yes No known. Pumped thro	Cover Damage  Yes No  ough inspection pipe.	conr <u>irm precase via</u>	
Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes No Some answers un	Leaking In  Yes No known. Pumped thro	Cover Damage  Yes No- pugh inspection pipe.  Yes No	conr <u>irm precast via</u>	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out  Yes No Some answers un Yes No Yes No Yes No	Leaking In  Yes No known. Pumped thro Yes No  Yes No	Cover Damage  Yes No ough inspection pipe.  Yes No Yes No	conr <u>irm precase via</u>	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were removed	Leaking Out    Yes   No	Leaking In  Yes No known. Pumped thro Yes No Yes No Yes No	Cover Damage  Yes No ough inspection pipe.  Yes No Yes No Yes No		
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were removed Tank #1 1250 gal Tank #2	Leaking Out  Yes No Some answers un Yes No Yes No Yes No Yes No Yes No	Leaking In  Yes No known. Pumped thro Yes No Yes No Yes No Yes No	Cover Damage  Yes No ough inspection pipe.  Yes No Yes No Yes No Pres No Pres No	gal	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were removed Tank #1 1250 gal Tank #2  5. Other information: List any troubleshooting	Leaking Out  Yes No Some answers un Yes No Yes No Yes No Yes No Pes No Real Pretreatment Real Pretreatment Real Pretreatment Real Pretreatment Real Pretreatment	Leaking In  Yes No known. Pumped thro Yes No Yes No Yes No Yes No	Cover Damage  Yes No ough inspection pipe.  Yes No Yes No Yes No Pres No Pres No	gal	
Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were removed Tank #1 1250 gal Tank #2	Leaking Out  Yes No Some answers un Yes No Yes No Yes No Yes No Pes No Real Pretreatment Real Pretreatment Real Pretreatment Real Pretreatment Real Pretreatment	Leaking In  Yes No known. Pumped thro Yes No Yes No Yes No Yes No	Cover Damage  Yes No ough inspection pipe.  Yes No Yes No Yes No Pres No Pres No	gal	

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718