## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Main	tenance 10/27/22	Reason for Maintenance:		CANCEL MODE	1441
Property Add	ress: 9614 2041	th st Ct N Pro	perty Owner's Name:		
	Forest Lake	State MJ Zip Co	de 55025 GE	O Code/Property I.D. #:	
Wha	was done (othersystem	A Later from	a rivience disking (e)	ໂຮຍຫຼືນໄປປະຕິເຊີຍ ກໍ່ເຊີຍ ກໍ່	
Tank(s) Pu	•		<b>A.</b>		
Sludge and	scum measured.	Liquid Level of Ta	in. Slud	lge Level in. Scum Le	evel in.
	eed to be pumped? No (If no provide measu	Total (Sludge + S	cum) / Liquid	Level = % Sludge &	k Scum
		faintenance Hole Other	(Go to #3 below)	* Tank must be pumpe	
		covers securely replaced?	_	ic constants and a second	
Explanation:					
3. If owner refu them comple	ises to allow a Subsurface te and sign the following	e Sewage Treatment System g statement:	m (SSTS) to be pumpe	d through the maintenance	hole, have
4, .		(Owner's name) refuse to	allow the removal of a	olids and liquids through the r	
hole. I unders	tand that removal of solid	s and liquids through other a	ccess points is not con	olids and liquids through the r	maintenance
4. Is the tank de	signed as a leaky tank? exa	imple: seepage pit, cesspool, d	rywell, leachina pit	sidered manitenance.	
	es - ATVo Verificatio Me		¥:		
Tank#2 🔲 Y	es No Verificatio Me	ri -			
5. Is there evide damaged, cra	nce of tank leakage from cked, or structurally unsc	a septic, holding, pretreat ound maintenance hole cov	ment or pump tank bo	elow the operating depth or	evidence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⊞No	☐ Yes ➡No	Yes - No	
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	Yes No	· ·
	Pretreatment Tank	Yes No	Yes No	Yes No	
i v	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gal	lons of septage were rem	noved?		E 100 E NO	
Tank#1 1350	Tank #2	Pretreatment Tan	kPı	ump Tank	
7. Other informat	ion: List any troubleshoo	oting, minor repairs conduc	ted, tank safety conc	erns, or other concerns.	
8. Certification: 1	hereby certify as a State o and made the observations	f Minnesota certified SSTS Ma s, or directly supervised other	aintainer that I persona is in the performance o	lly conducted the work f this job.	<u> </u>
	ne: Olson's Sewer Service		122	Street NE, Forest Lake, MN	
Maintainer's Lice	ense #: 216 Main	ntainer's Phone #: 651-464-2	2082	ı	
Maintainer's Sigi	nature M/	1	Date: 10,	127/22	