

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Property Address: 5133 Wild Canyon Dr Wododbury Property Owner's Name: Mike Knajek Municipality: ZIP: 55129 Property Identification Number: Maintainer Name and License No. Schlomka Service LLC/L2989 Maintenance Permit No: Maintainer Name and License No. Schlomka Service LLC/L2989 Maintenance Performed	Date of Maintenance:	10/27/22 Reason f	for Maintenance: _	Routine		
Maintenance Permit No:	Property Address: 51	33 Wild Canyon Dr Wodod	bury Pr	operty Owner's N	ame:N	/like Knajek
Maintenance Permit No:	Municipality:	ZIP: 5512	9 Property Ident	tification Number:		
Tank(s) Pumped						
Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements) Sludge & Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater Tanks must be pum	Maintena	nce Performed	Tank Measu	rement (must be	completed if tanks	NOT pumped)
2. Were all covers securely replaced?	Do tanks need to	be pumped?	Sludge Level in T	ank in / Liquid L	evel X 100)
Septic/Holding Tank #1	2. Were all covers se	curely replaced? 🖯 Yes [∃ _{No} N/A		tank below the opers? <u>No-couldn't</u>	erating depth or confirm precast via
Some answers unknown. Pumped through inspection pipe. Septic/Holding Tank #2		Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2		Septic/Holding Tank #1				
Pump Tank		Septic/Holding Tank #2		•	200	
4. How many gallons of septage were removed? Tank #1 1500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.		Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.		Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.				took -	al Dump Tank	ادم
Some answers unknown. Pumped through inspection pipe.	5. Other information	i: List any troubleshooting,	minor repairs con	ducted, tank sare	ety concerns, or ou	ier concerns.
6 Location of sentage disposal: Metro MCFS WWTP			tion pipe.	with the second		

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718