Compliance criteria:		Attached supporting documentatio	n:
System discharges sewage to the ground surface	☐ Yes* ☒ No	☐ Other: ☐ Not applicable	***
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No		
Any "yes" answer above indicates imminent threat to public health ar			
nk integrity – Compliance Compliance criteria:	component #2		n:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	Attached supporting documentatio ⊠ Empty tank(s) viewed by inspector	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their		Attached supporting documentatio Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business	Meyers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☒ No	Attached supporting documentatio ☑ Empty tank(s) viewed by inspector Name of maintenance business:	Meyers ess: 11/02/20
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documentatio Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busine Date of maintenance: Existing tank integrity assessment (Attached)	Meyers ess: 11/02/20 ach)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentatio Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busine Date of maintenance: Existing tank integrity assessment (Attached)	Meyers ess: 11/02/20 ach) nin three year
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Maintenance) (mm/dd/yyyy): (See form instructions to ensure asses Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not neces	Meyers ess: 11/02/20 ach) nin three year sment compli
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance busines Date of maintenance: Existing tank integrity assessment (Attached Mind Mind Mind Mind Mind Mind Mind Min	Meyers ess: 11/02/20 ach) nin three year sment compli