

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed <u>prior</u> to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	or Maintenance: _		<del>-</del>	
Property Address: 8548 Hidden Bay Trl Lake Eln	no, MN P	roperty Owner's Na	ame: Eric Abrahar	m
Municipality: ZIP: 55042	2 Property Ider	ntification Number:		
Maintenance Permit No: Ma	aintainer Name an	d License No. Sch	lomka Service LLC	C/L2989
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
☑ Tank(s) Pumped		ank in		
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			evel X 100	
$\square$ Yes $\square$ No (if no provide measurements)	= % Studge & Sct	ıııı ıaı	iks must be pumped	II 23% Of greater
1. Access used to remove septage:   Maintenand	so Holo 💆 Other (s	enter authorization co	nde)	
		inter authorization co	ide)	
2. Were all covers securely replaced?				
3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura	ic, holding, pretr lly unsound main	eatment or pump tenance hole cove	tank below the ope rs? <u>No-couldn't</u>	rating depth or conf <u>irm precast via</u>
			camera	
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No			
, , ,	Some answers un	known. Pumped thro	ugh inspection pipe.	
Septic/Holding Tank #1 Septic/Holding Tank #2	Some answers un		ugh inspection pipe.	
, , ,	Some answers un	known. Pumped thro	ugh inspection pipe.	
Septic/Holding Tank #2	Some answers unl	known. Pumped thro	ugh inspection pipe.	
Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Yes No Yes No Yes No	known. Pumped thro	ugh inspection pipe.  Yes No  Yes No	
Septic/Holding Tank #2 Pretreatment Tank Pump Tank  4. How many gallons of septage were removed?	Yes No Yes No Yes No	Known. Pumped thro	ugh inspection pipe.  Yes No  Yes No  Yes No	gal.
Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2	Some answers und  Yes No  Yes No  Yes No  gal Pretreatmen	known. Pumped thro	ugh inspection pipe.  Yes No Yes No Yes No Pes No	
Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #11500 gal Tank #2  5. Other information: List any troubleshooting,	Yes No Yes No gal Pretreatment	known. Pumped thro	ugh inspection pipe.  Yes No Yes No Yes No Pes No	
Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2	Yes No Yes No gal Pretreatment	known. Pumped thro	ugh inspection pipe.  Yes No Yes No Yes No Pes No	

Schlomka Services, LLC 1904 Vermillion St. Hastings, MN 55033 License# 2989 P: 651-459-3718