DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Mai	ntenance Re	eason for Maintenance:	m4848K	29234	
Property Ad	dress: 21303 @m	My Ave.	Property Owner's Name:	Zachary ,	Sacrill
Municipality	Sca-dia	State Zip	Code GE	O Code/Property I.D. #:	- Stepl
	(twasdone to the system)	建	Measurements Influen	asquiplication in among	
Tank(s) Pu	mped :		Child Child		
	d scum measured.	Liquid Level of	Taifk in. Slud	lge Level in. Scum L	.evel in.
The second	need to be pumped?	Total (Sludge +	Scum) / Liquid	Havel - Webst-	
	No (If no provide measure	ements)			
7. Access used	I to remove septage: Ma	intenance Hole 🔲 Oth	er (Go to #3 below)	* Tank must be pump	ed if this value
2. If maintenar	nce hole was used, were all co	overs securely replaced?	Yes No please e	is greater than 25%, xplain	,
Explanation					
3. If owner ref	uses to allow a Subsurface !	Sewage Treatment Syst	em (SSTS) to be pumpe	d through the maintenance	e hole have
	ete and sign the following s	statement:			- 11010/11010
',		(owner's name), refuse	to allow the removal of so	olids and liquids through the	Maintenance
hole. I under	stand that removal of solids a	ing liquids through othe	r access points is not con:	sidered maintenance.	· · · · · · · · · · · · · · · · · · ·
4. Is the tank de	signed as a leaky tank? exam	ple: seepage pit, cesspool,	drywell, leaching pit		
Tank#1	es No Verificatio Meth	od Used:			
Tank#2 🗀 y	es No Verificatio Meth	dilent			
	~				
damaged, cra	ence of tank leakage from a cked, or structurally unsou	septic, noiding, pretrei nd maintenance hole c	atment or pump tank be overs?	elow the operating depth o	r evidence of
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	Yes Tho	Yes No	-
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	ŧ.,
	Pretreatment Tank	Yes No	Yes No	Yes No	•
(ē	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	ži.
6. How many gai	lions of septage were remov	ved?			
Tank#1 / 8	()() Tank#2 100	Pretreatment Ta	nk n.		
7 Other informa				ımp Tank	
Oniei Iutolwa	tion: List any troubleshooti	ng, minor repairs condi	ucted, tank safety conce	rns, or other concerns.	
9 Contification	The second second				
o. Cerunication:	I hereby certify as a State of N and made the observations, c	Minnesota certified SSTS (or directly supervised oth	Vlaintainer that I personal	ly conducted the work	
	me: Olson's Sewer Service, I				
			13 Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's Lic	ense #: 216 Mainta	iner's Phone #: 651-464	-2082	t	
Maintainer's Sig	nature A	9-	Date: /	1-14-22	
	9	Z.			