

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

<del>-</del> 1:	ompleted in its entirety t	o constituto a vali	d maintenance ne	rmit This permit m	just be completed
	ing maintenance activitie				
			7 - L		,
Date of Maintenance:	Reason f	or Maintenance: 샃	EUTIL	/	
Property Address: 80	80 1191 St	Pr	operty Owner's Na	me: LINCLA	Langsa
Municipality: Sill	WHEN ZIPSSON	2 Property Iden	tification Number:		
Maintenance Permit No:	18674277696 M	aintainer Name and	d License No. Pinky	r's Environmental Sev	wer Service/ L1673
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank ——— in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	urely replaced? Yes tank leakage from a septed, cracked, or structura	tic, holding, pretre	eatment or pump	tank below the oper	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of	of septage were removed?				
Tank #1 15 50	gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or othe	er concerns.
	200	thing			
			+ 0/1	· c+ 01	
6. Location of septage	disposal: h/h	Illeton	en PINT	) WHO	
	Dielect	- Faviranmantal Co	war Sanica Inc		
	Pinky	s Environmental Se	wei service inc.		

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673