

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a	valid maintenance	permit This permit	
<u>prior</u> to performing maintenance activit	ies and remain o	n-site for the dur	permit. This permit	t must be completed
Date of Maintenance: 7-1-16 Reason	for Maintonance	. Pontin A	ation of the mainten	ance activity.
Property Address: 1582 Novem Ae	1 Y s	Runu	1 11 - 2	200
AA				y Mosser
		entification Numbe		
Maintenance Permit No: 1629543216 M	laintainer Name	and License No. Pi	nky's Environmental	Sewer Service/L1673
Maintenance Performed	Tank Mea	asurement (must b	e completed if tanks	s NOT pumped)
✓ Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers securely replaced?  Yes</li> <li>Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural</li> </ol>	ic, holding, pret Ily unsound mair	reatment or pump	tank below the ope ers?	erating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	✓ Yes □ No	✓ Yes □ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☑ Yes ☐ No	Yes No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 750 gal Tank #2 250	gal Pretreatment	t tankg	al Pump Tank	anl
5. Other information: List any troubleshooting, n	ninor repairs co	nducted, tank safe	ty concerns, or othe	gal er concerns.

Maintenance activities must be reported to the Department within 90 days.