

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing main	ntenance activitie	es and remain on	site for the duration	on of the maintena	nce activity.	
Date of Maintenance: 8-12-16 Reason for Maintenance:						
Property Address: 8365 Rive Acres Rd Property Owner's Name: Riby Susan Hunsey						
Municipality: Cuttage Gove ZIP: Property Identification Number:						
Maintenance Permit No: <u>y & 391 e 379 L</u> Maintainer Name and License No. Pinky's Environmental Sewer Service/L1673						
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped	Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped	Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Schwarted Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Hol	ding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Hol	ding Tank #2	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☐ No		
Pretreatm	ent Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tanl	(☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage	were removed?					
Tank #1 / Doo gal Tank #2 / Doo gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage disposal:	St. Ja	/				

Maintenance activities must be reported to the Department within 90 days.