

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed | | |
|--|--------------------------|--|
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | | |
| Date of Maintenance: 18 2 Reason for Maintenance: 18 Mg 47 | | |
| Property Address: | 1077 Store | or digety Property Owner's Name: Richard + and Martens |
| Municipality: | rater ZIP:5500 | Property Identification Number: |
| Maintenance Permit No: 192442947/ Maintainer Name and License No. Smilie's Sewer Service / L 2428 | | |
| | | Similar Service 7 E 2420 |
| Maintena | nce Performed | Tank Measurement (must be completed if tanks NOT pumped) |
| Tank(s) Pumped | | Liquid Level of Tank in |
| Sludge and scum | measured | Sludge Level in Tank in Scum Level in Tank in |
| Do tanks need to | be pumped? | Sludge + Scum / Liquid Level X 100 |
| Yes No (if | no provide measurements) | = % Sludge & Scum Tan <u>ks must be pumpedif 25% or greate</u> r |
| 1. Access used to remove septage: Maintenance HoleOther (enter authorization code) | | |
| 2. Were all covers securely replaced? Yes No | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or | | |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? YesNo | | |
| | Tank | Leaking Out Leaking In Cover Damage |
| | Septic/Holding Tank #1 | Yes Yes Yes LATO |
| | Septic/Holding Tank #2 | _ Yes _ No _ Yes _ No |
| | Pretreatment Tank | Yes No Yes No Yes No |
| | Pump Tank | Yes No Yes No Yes No |
| 1. How many gallons of septage were removed? | | |
| Tank #1 800 | _gal Tank #2_000 g | al Pretreatment tankgal Pump Tankgal |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | |
| | | |
| 5. Location of septage disposal: | | |
| | | Smilie's Sewer Service P.O. Box 100 Scandia, MN 55073 |
| | P: 651-4 | 33-3934 License Number: L2428 |
| Maintenance activities must be reported to the Department within 90 days. | | |
| | | |

White Copy-Maintainer submits to Washington County / Yellow Copy-Property Owner Record