DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT W6154H 29244

Date of Maintenance 11-22 27 R	leason for Maintenance:	Dim	1	
Property Address: 20210	de Alexant	Property Owner's Name:	Steve & colette	2 V
Municipality:			EO Code/Property I.D. #:	(2004h
What was done to the system.			 រត្តសម្រាប់ ស្រីស្រាស់ ស្រីស្រីសុខ ស	1. E. VIII. 2012 PRIVATE
☐ Tank(s) Pumped	11	-	eas Amhaice an chuchtoil	(umped)
Sludge and scum measured.	Liquid Level of	Tafik in. Sluc	dge Level in. Scum	Level ir
Do tanks need to be pumped? Yes No Uf no provide measure	Total (Sludge 4	Scum) /	•	
in the provide incustre	ements)		d Level = % Sludge	€&Scum
1. Access used to remove septage:	intenance Hole []Oth	er (Go to #3 below)	* Tank must be pum	ped if this valu
2. If maintenance hole was used, were all co	overs securely replaced?		Is greater than 25%	5.
Explanation:			s.p.un	-
3. if owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Syst	em (SSTS) to be pumpe	d through the maintenance	rahata tam
_	itatement:	¥.	and the manifelialit	e noie, nave
hele to the	(owner's name), refuse t	to allow the removal of s	olids and liquids through the	maintenare.
hole. I understand that removal of solids a	אווס וועטוט: נוווסטטון סנחפו	l access boints is not con	sidered maintenance.	· mantenance
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool,	drywell, leaching pit		
Tank#1 Yes No Verificatio Meth	od Used:			
Tank#2 Yes No Verificatio Meth				
is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretrea nd maintenance hole co	itment or pump tank be	elow the operating depth o	r evidence of
Tank	Leaking Out	Leaking in	Cover Damage	
Septic/Holding Tank #1	Yes No	☐ Yes No		- 55
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	š
6. How many gallons of septage were remove	/ed?		[142 [140	Œ
Tank #1 1320 Tank #2	Pretreatment Tar	nk PL	ımp Tank	
7. Other information: List any troubleshootis	ng, minor repairs condu	cted, tank safety conce	rns, or other concerns.	
9 Constitue				
8. Certification: I hereby certify as a State of M and made the observations, o	linnesota certified SSTS N r directly supervised othe	laintainer that I personal ers in the performance of	ly conducted the work	
Maintainer's Name: Olson's Sewer Service, In		•	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintai	ner's Phone #: 651-464-		t	
Maintainer's Signature		Date:	-22.22	