ess Name: SS Septic Solutions, LLC	`ompliance comp		2/13/2022
Compliance criteria:	omphance com	Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No	_ погаррисаве	
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No		
Any "yes" answer above indicates imminent threat to public health a			1
Describe verification methods and	d results:		
2			
nk integrity – Compliance	e component #2	of 5	
nk integrity — Compliance Compliance criteria:	e component #2	of 5 Attached supporting documentation:	
Compliance criteria: System consists of a seepage pit,	e component #2		
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,		Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?		Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business:	Meyer's
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	□ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business	Meyer's
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	□ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance:	Meyer's s: 12/13/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	□ Yes* ⊠ No	Attached supporting documentation: ⊠ Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: □ Existing tank integrity assessment (Attack	Meyer's s: 12/13/2022
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	□ Yes* ⊠ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance:	Meyer's s: 12/13/2022 h)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within	Meyer's s: 12/13/2022 h) three years)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1))	Meyer's s: 12/13/2022 h) three years) nent complies
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within	Meyer's s: 12/13/2022 h) three years) nent complies
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment) Minn. R. 7082.0700 subp. 4 B (1))	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ test ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicis failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ test ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicis failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ test ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicis failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ test ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indicis failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ test ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attack Date of maintenance (mm/dd/yyyy): (must be within (See form instructions to ensure assessment Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necess	Meyer's s: 12/13/2022 h) three years) nent complies ary – explain be

800-657-3864