## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT 19871629248

Date of Ma	intenance 12/2/22 R	eason for Maintenance:			0. 101
Property A	odress: 1590/ Ingerso	oll Ave N	Property Owner's Name:		*
Municipalit			Code 55038 GE	O Code/Property I.D. #:	
AND SHOP THE REAL PROPERTY.	ictoristations (Minery (emy	a de la como	Measurement simusab	asopplication devolu	
Tank(s)		Liquid Level of	- A.		
Sludge and scum measured.  Do tanks need to be pumped?		riduid teksi Oi	in. Sluc	lge Level in. Scum i	Level ii
Yes	No (If no provide measure	Total (Sludge +	Scum) / Liquid	i Level = % Sludge	& Scum
1. Access use	d to remove septage: Ma				
2. If maintena	ance hole was used, were all co	Mate section to persons	er (Go to #3 below)	<ul> <li>Tank must be pumpled is greater than 25%</li> </ul>	ped if this valu
Explanation		overs securely replaced?	Yes No please e	xplain —	
•		Courses Transfer	40-00		
them comp	fuses to allow a Subsurface : lete and sign the following :	sewage Treatment Syst statement:	em (SSTS) to be pumpe	d through the maintenanc	e hole, have
1,		(OWner's name) refuse	en allacciation and the		
hole. I unde	rstand that removal of solids a	owner's name), refuse t	o allow the removal of so	olids and liquids through the	maintenance
4. Is the tank d	esigned as a leaky tank? exam	ple: seepage nit cessoool	access points is not con:	sidered maintenance.	
	Yes No Verificatio Meth				
			/		
	Yes No Verificatio Meth				•
5. is there evid damaged. cr	lence of tank leakage from a acked, or structurally unsou	septic, holding, pretrea	tment or pump tank be	elow the operating depth o	T evidence of
	Tank	Leaking Out	1		,
	Septic/Holding Tank #1	Yes No	Leaking In	Cover Damage	_
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
	Pretreatment Tank	Yes No	Yes No	Yes No	
-	Pump Tank	☐Yes ☐No	Yes No	Yes No	
6. How many ga	alions of septage were remov	ved?			
Tank#1 900	Tank #2	Pretreatment Ta	nk pı	ımp Tank	
7. Other informa	ation: List any troubleshooti	NG. Minor ronaise cond.			
		g,or repairs collec	icted, tank sarety conce	rns, or other concerns.	
8. Certification:	I hereby certify as a State of M	linnesota certified SSTS A	Asintsinor that I marrow at		·
	and made the observations, o	or directly supervised other	ers in the performance of	ly conducted the work this job.	
	ame: Olson's Sewer Service, Ir		•	Street NE, Forest Lake, MN	
Maintainer's Lic	cense #: 216 Maintai	iner's Phone #: 651-464		, and conc. latta	
Maintainer's Sig		4		V 10	
	anarole	X	Date: 12/	2/22	