## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT 0.8694x29251

Date of Maintenance	と Reason for Maintenance:	>m		010
Property Address: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ka mago trail	Property Owner's Name:	MATT Hein	
Municipality:	1	((27)7	O Code/Property I.D. #:	
we aWhitevasdone (other)	Venita de la participa de la p	Mensurements (musca)	awoolaa Herokaaloo	744 K362
Tank(s) Pumped	Liquid Level o	e- A.		
Sludge and scum measured.  Do tanks need to be pumped?	Fidata FEAEI O	In. Sluc	ige Level in. Scum Le	vel in
Yes No (If no provide m	reasurements) Total (Sludge	Scum) / Liquid	Level = %Sludge &	Scum
1. Access used to remove septage:		ier (Go to #3 holow)	* Tank must be pumpe	
2. If maintenance hole was used, were	e all covers securely replaced?	Yes No please e	is greater than 25%	o ii this value
Explanation:				
<ol><li>If owner refuses to allow a Subsuithem complete and sign the follow</li></ol>	rface Sewage Treatment Sys wing statement:	tem (SSTS) to be pumpe	d through the maintenance	hole, have
<b>l,</b> ·		An affect of		
hole. I understand that removal of s	olids and liquids through other	to allow the removal of so	olids and liquids through the n	naintenance
4. Is the tank designed as a leaky tank?	example: seepage pit, cesspool	drivell. leaching nit	sidered maintenance.	
	Method Used:	and the second property of the second propert		
	ہ ————— Method Used:			•
<ol><li>is there evidence of tank leakage for damaged, cracked, or structurally t</li></ol>	rom a septic, holding, pretre insound maintenance hole c	atment or pump tank be	low the operating depth or o	evidence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank	#1 Yes No	Yes No	Yes Who	
Septic/Holding Tank	2 Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were	removed?			
Tank#1 Tank#2	Pretreatment Ta	7 W	mp Tank	
7. Other information: List any troubles	hooting, minor repairs cond	acted, tank safety conce	rns, or other concerns.	
8. Certification: I hereby certify as a Stat and made the observati	e of Minnesota certified SSTS I ons, or directly supervised oth	Maintainer that I personall	y conducted the work	
Maintainer's Name: Olson's Sewer Sen		's Address: 17638 Lyons S		
Maintainer's License #: 216 M	aintainer's Phone #: 651-464		1	
Maintainer's Signature		Date:   2-	6-22	