## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintenance 1 27 33 R	eason for Maintenance:	9 695502	9358	
Property Address: 15385 Self	. Or. April	Property Owner's Name	Ken Buss	
Municipality:	State Zip	Code 55038 GE	O Code/Property I.D. #:	
2.2.2. aWhatewasdone of the spateing	i tegjalik	Mariumarana karri (65	iopla: Anadoni.	1041K3X1
Tank(s) Pumped				
Sludge and scum measured.	Liquid Level of	Tarik in. Sluc	lge Level in. Scum Leve	el ir
Do tanks need to be pumped?	Total (Sludge 4	Scum) / 1:		
Yes No (If no provide measure	ements)		Level = %Sludge & S	cum
1. Access used to remove septage:Ma	intenance Hole Oth	er (Go to #3 below)	* Tank must be pumped	if this valu
2. If maintenance hole was used, were all co				
Explanation:				
<ol><li>If owner refuses to allow a Subsurface them complete and sign the following:</li></ol>	Sewage Treatment Syst	em (SSTS) to be pumpe	d through the maintenance h	ole, have
hole. I understand that removal of solids a	owner's name), refuse	to allow the removal of so	olids and liquids through the ma	intenance
4. Is the tank designed as a leaky tank? exam	nie: seenas triibugi otne	decess points is not con:	sidered maintenance.	
_ , \				
Tank#1 Yes No Verificatio Meth	od Used: Visua	x (		
Tank#2 Yes No Verificatio Meth				
<ol><li>Is there evidence of tank leakage from a damaged, cracked, or structurally unsou</li></ol>	septic, holding, pretre	atment or pump tank be	low the operating depth or ex	idence of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ► No	Yes - No		
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gallons of septage were remove	red?		Yes No	
Tank #1 1600 Tank #2	Pretreatment Ta	nk Pi	ımp Tank	
7. Other information: List any troubleshooti	ng, minor repairs cond	icted, tank safety conce	rns, or other concerns.	
9 Foulth 11				
8. Certification: I hereby certify as a State of N and made the observations, o	linnesota certified SSTS I or directly supervised oth	Naintainer that I personal ers in the performance of	ly conducted the work this job.	
Maintainer's Name: Olson's Sewer Service, Ir			Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintai	iner's Phone #: 651-464			
Maintainer's Signature	The state of the s	Date: //	26/23	