

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 FIVE Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

JAN 1 3 2023

4	System Loc	cation	PUBLIC HE
Address 12/078 Homest			phone Number
	tugo State MNZI	P 55116 Property II	D No./GEO Code
Owner	Pumping Date	7/19/22	F
	Contrac		
Maintainer DT Septic Services	MPCA License N	o. #3663 Telep	ohone Number (763) 286-1815
What was done to the syst	em?	Report Liq	uid Capacity in Gallons
☐ Sludge and scum measured. ☐ Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measured) Visual Inspection (note any problem)		Tank 3: 1000 100 Pur Total Gallons Pumped:	mped Tank 2: 1000 Pumped Pumped Tank 4: Pumped Pumped Pumped Serve as a compliance inspection
* Tan Liquid Level of Tank (Distance from inve	k Measurements-Use Only I		ped
Sludge Level in. + Scum Lev	el in. = Total Sludg	ge and Scum Level	
Total Sludge and Scum Level	/ Liquid Level	= Percent Sludge	*Tanks must be pumped if either of the following conditions exist: 1. The top of the sludge layer is less
Scum Layer Effluent Sludge Layer		Liquid Level measured from invert of outlet pipe to bottom of tank	than 12 inches from the bottom of the outlet baffle; or 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.
Signature	Date		Reset Form