

RECEIVED

NOV 13 2023

PUBLIC HEALTH

## SSTS MAINTENANCE REPORT

System Location			
Address <u>20640 Keewahat Ave</u>		Telephone Number	
City <u>Forest Lake</u>	State <u>MN</u> ZIP <u>55025</u>	Property ID No./GEO Code	
Owner <u>Merri Voiss</u>		Pumping Date <u>11/3/22</u>	
Contractor			
Maintainer <u>DT Septic Services</u>	MPCA License No. <u>#3663</u>	Telephone Number	<u>(763) 286-1815</u>

**What was done to the system?**

Tank(s) Pumped

Sludge and scum measured.

Do tanks need to be pumped?

Yes  No (If no provide measurements below)

**Report Liquid Capacity in Gallons**

Tank 1: 1000  Pumped Tank 2: \_\_\_\_\_  Pumped

Tank 3: \_\_\_\_\_  Pumped Tank 4: \_\_\_\_\_  Pumped

Total Gallons Pumped: 1000

Visual Inspection (note any problems with the system):


NOTE: This does not serve as a compliance inspection.

**\*Tank Measurements-Use Only If Tank(s) Were NOT Pumped**

Liquid Level of Tank (Distance from invert of outlet pipe to bottom of tank) \_\_\_\_\_ in.

Sludge Level \_\_\_\_\_ in. + Scum Level \_\_\_\_\_ in. = Total Sludge and Scum Level \_\_\_\_\_

Total Sludge and Scum Level \_\_\_\_\_ / Liquid Level \_\_\_\_\_ = Percent Sludge and Scum in Tank \_\_\_\_\_ %



\*Tanks must be pumped if either of the following conditions exist:  
 1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or  
 2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.

Signature B. M.

Date 11/3/22

Reset Form