



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	e: 11-9-17 Reas	on for Maintenance	: Regular			
Property Address:	9300 Harrow	Are North	Property Owner's	Name: Sao Yo	ang	
	st Lake ZIP: 59				J	
Maintenance Permit	No: 8906299712) Maintainer Name	and License No. 0	Isrus Sewer Sc	rvice # 216	
	,					
Maintenance Performed		Tank Me	Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?			Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
		Sludge Level in				
		11				
☐ Yes ☐ No (if no provide measurements)		s) = % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: 🛱 Mainten	ance Hole Other	enter authorization (code)		
2. Were all covers se	curely replaced? X Yes	□No				
	of tank leakage from a se aged, cracked, or structu		reatment or pump	tank below the ope	erating depth or	
evidence of dam	aged, cracked, or structu	rally unsound mair	ntenance hole covi	ers? No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 风No	☐ Yes 🌣 No	☐ Yes 🎞 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed:	7				
	gal Tank #2		tank øa	l Pump Tank	αal	
	List any troubleshooting,					
×	,		,	,	. concerns,	
. Location of septage	disposal: Mcto					