

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a va	alid maintenance p	permit. This permit r	must be complete	
	orming maintenance activit					
Date of Maintenance	@ 11 22	for Maintenance:				
Property Address:	498 Stillweiter	Bleeno	Property Owner's N	Name: Valeng	Mielsen	
Municipality: (1)	Elma ZIP: 50	17 Property Ide	ntification Number	•		
Maintenance Permit	No: <u>C3127+78699</u> N					
mantenance i crime	NO. COTOC COOT IN	name al	nd License No. Pink	(y's Environmental Se	wer Service/ L167	
Mainten	ance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank ——— in				
☐ Sludge and scum	measured Sludge Level in Tank — in Scum Level in Tank in					
Do tanks need to						
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
	move septage: Maintenar		enter authorization c	oder Too DIE		
3. Is there evidence	of tank leakage from a sep	tic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
evidence of dam	aged, cracked, or structura	ally unsound main	tenance hole cove	ers? Yes No	and acpair of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed?					
Tank #1 11 00	gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal	
	: List any troubleshooting,					
		, 1	1			
6. Location of septage	e disposal: NW Tree	etment Dim	+ St. Pm			
				P 1		
	Pinkv's	Environmental Se	wer Service Inc			
		DO Poy 35				

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673