

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

l .	completed in its entirety t					
Date of Maintenance:	8-(5-22 Reason f	or Maintenance:	Reutine			
Property Address: 1581 Olene Arc 10 Property Owner's Name: Steve Schultz						
Municipality: Still	cuto zip:3868	Property Iden	tification Number:		_	
Maintenance Permit N	0: <u>19244 v 28102 m</u>	aintainer Name an	d License No. Pinky	r's Environmental Sew	er Service/ L167	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped		Liquid Level of Tank — in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? ✓ Yes ☐ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? ☐ Yes ☒ No 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☑ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed? Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal						
5. Other information	: List any troubleshooting,	minor repairs cor	nducted, tank safe			
6. Location of septage		n M - WW.	113 - 119			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673