

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety			1117		
	8.8.25 Reason		RCIALIA		·	
	1		Acoura	10	E	
Property Address:	oro Kimbro U	n lo p	roperty Owner's Na	ame: WWW V	adnai	
Municipality:	water zip: 5508	Property Iden	ntification Number:			
Maintenance Permit N	0: <u>C6494£28121</u> A	Naintainer Name ar	d License No. Pinky	y's Environmental Sev	wer Service/ L1673	
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Rumped		Liquid Level of	Liquid Level of Tank ——— in			
☐ Tank(s) Pumped ☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? ✓ Yes ☐ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? ☐ Yes ☐ No 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
1 .	of septage were removed		tank	al Pump Tank	nal	
	: List any troubleshooting,					
6. Location of septage		's Environmental Se	ewer Service Inc.			
		PO Boy 35	1			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673