

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire		
	vities and remain on-site for the durat	ion of the maintenance activity.
Date of Maintenance: 10-31-22 Reas	on for Maintenance: Kathu	
Property Address: 2720 Have	Are So Property Owner's N	ame: Bruce Anderson
	Property Identification Number	•
Maintenance Permit No: V619279380	Maintainer Name and License No. Pink	y's Sewer Service Incorporated/ L4251
Maintenance Performed	Tank Measurement (must be	completed if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Tank — in	
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in	
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100	
$\square$ Yes $\square$ No (if no provide measurement	s) = % Sludge & Scum Ta	nks must be pumped if 25% or greater
1. Access used to remove septage: $\square$ Mainte	nance Hole Other (enter authorization co	ode) Too Did
2. Were all covers securely replaced? Ye		1000
<ol><li>Is there evidence of tank leakage from a s evidence of damaged, cracked, or structor</li></ol>	eptic, holding, pretreatment or pump urally unsound maintenance hole cove	tank below the operating depth or rs?  Yes No
Tank	Leaking Out Leaking In	Cover Damage
Septic/Holding Tank #1	☐ Yes ☑ No ☐ Yes ☑ No	☐ Yes ☐ No
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No
4. How many gallons of septage were remove	ed?	
Tank #1/250 gal Tank #2	gal Pretreatment tankga	al Pump Tank gal
<ol><li>Other information: List any troubleshooting</li></ol>	g, minor repairs conducted, tank safe	ty concerns, or other concerns.
nothing		
	0/1	
6. Location of septage disposal:	cetment/Int & for)	

Pinky's Sewer Service Incorporated

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L4251