Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety t	o constitute a v	alid maintenance p	permit. This permit	must be completed
prior to perfo	orming maintenance activiti	es and remain o	n-site for the dura	tion of the maintena	ince activity.
Date of Maintenance	: 10.21.22 Reason f	or Maintenance:	Routine		
Property Address: \(\sum_{\text{\ti}\text{\texi{\text{\texi{\text{\texi{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\text{\text{\texi{\text{\texi{\text{\texi{\texi}\text{\text{\text{\text{\text{\texi{\text{\texi}\text{\texi}\text{\texi	3134 40° St	50	Property Owner's N	Name: Kevin T	Bonine
Municipality: Aft	zip: <u>550</u>	Property Ide	entification Number	r:	
Maintenance Permit	No: r9763729172 M	aintainer Name a	nd License No. Pink	«v's Environmental Se	ewer Service / 11672
				y - monimental se	Wel Service/ L10/3
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage: Maintenance	e Hole Other (enter authorization co	ode) FMH Was	10 kansa
2. Were all covers se	ecurely replaced? Yes	No			
			reatment or nume	mainline	pluggie
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No	
I. How many gallons	of septage were removed?				
Tank #1 2 >>>	gal Tank #2 🗾 🗷 g	al Pretreatment	tankga	al Pump Tank	gal
. Other information	: List any troubleshooting, m	ninor repairs cor	ducted, tank safet	ty concerns, or other	r concerns
	20thin	5			concerns.
				1	
. Location of septage	disposal:	eatmenth	Plant stran		
	Pinky's E	nvironmental Se	wer Service Inc.		
DO P 25 4					

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673