

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be com	pleted in its entirety to	o constitute a val	id maintenance pe	rmit. This permit m	ust be completed
prior to performing Date of Maintenance:	maintenance activitie	es and remain on or Maintenance:	DOM MI	on of the maintenand	ce activity.
Property Address:	24 Mana	LAA AUD P	Property Owner's Na	me: Pat I	TOOL
(LES)		1200		7 1	
Municipality:	12/10 ZIP:05/1	Property Idei	ntification Number:	<u> </u>	
Maintenance Permit No: 🙋	5/9Ct36C M	aintainer Name ar	id License No. Smili	ie's Sewer Service/L2	.428
Maintenance I	Periformed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove	septage: Maintenan	ce Hole 🗌 Other (e	enter authorization co	de)	
2. Were all covers secure	ly replaced? 🗗 Yes 🗆	□ No			
3. Is there evidence of ta		ic, holding, pretr	reatment or pump t tenance hole cover	tank below the operars?	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
Sep	tic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes 🗖 No	☐ Yes 🚺 No	
Sep	rtic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pre	treatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pur	mp Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of s	eptage were removed?		-		
				_	
	al Tank #2	gal Pretreatmen	t tankga	al Pump Tank	gal
	al Tank #2 at any troubleshooting,				
Tank #1 $\int 200$ ga					
Tank #1 $\int 200$ ga					