

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

		to constitute a va	alid maintenance p	permit. This permit mu	ust be completed	
<u>prior</u> to perf	orming maintenance activi	ties and remain or	n-site for the dura	tion of the maintenanc	ce activity.	
Date of Maintenance	: //-25-22 Reason	for Maintenance:	Rantine			
Property Address:	5210 Pannters	In Cir No	Property Owner's N	Name: Warre C	lianna	
Municipality: Muchto ZIP: 5508		Property Identification Number:			Brum	
Maintenance Permit	No: X7157929617	Maintainer Name a	nd License No. Pink	(y's Sewer Service Incor	porated/ L4251	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank — in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	of tank leakage from a sep aged, cracked, or structure Tank	tic, holding, pretr	reatment or pump tenance hole cove Leaking In	tank below the operaters?  Yes No  Cover Damage	ing depth or	
	Septic/Holding Tank #1					
		Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☑No	☐ Yes ☐ No		
	Septic/Holding Tank #2 Pretreatment Tank					
	10.	☐ Yes ☐ No	☐ Yes ☑No	☐ Yes ☐ No ☐ Yes ☐ No		
4. How many gallons	Pretreatment Tank  Pump Tank  of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
4. How many gallons Tank #1 <u>↓↓↓○</u> ○	Pretreatment Tank  Pump Tank  of septage were removed?	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1 <u> </u>	Pretreatment Tank Pump Tank	Yes No Yes No Yes No gal Pretreatment	Yes No Yes No Yes No tank ganducted, tank safet	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal :oncerns.	
Tank #1 ↓ U ∘ C 5. Other information  More	Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No tank ganducted, tank safet	Yes No Yes No Yes No Pump Tank ty concerns, or other of	concerns.	
Tank #1 ↓ U ○ C	Pretreatment Tank  Pump Tank  of septage were removed?  gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatment minor repairs con	Yes No Yes No Yes No Yes No tank ganducted, tank safet	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	concerns.	

Pinky's Sewer Service Incorporated

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L4251