

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	y to constitute a va	alid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to perfo	orming maintenance activi	ties and remain or	n-site for the durat	tion of the maintena	nce activity.	
	11-10-22 Reason					
Property Address:			Property Owner's N	lame: Roger Y	ncoler	
Municipality: 811	Water zip:58	287 Property Ide	entification Number	:		
	No: <u>115935 x 291321</u>				orporated/ L4251	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum				
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	ocurely replaced? Yes of tank leakage from a sep aged, cracked, or structur	otic, holding, preti	reatment or pump tenance hole cove	tank below the oper	ating depth or	
	Tank 	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	of septage were removed					
Tank #1 /7 (2)	gal Tank #2	and Duntun-to-		The state of the s		
Tank #1 /200	gal Tank #2	_gal Pretreatment	tankga	l Pump Tank	gal	
Other information:	gal Tank #2 : List any troubleshooting, old furnal 643	_gal Pretreatment , minor repairs cor	tankga	ty concerns, or other	gal concerns.	

Pinky's Sewer Service Incorporated

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L4251