

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

					AND THE RESIDENCE OF SHORE PROPERTY	
This section must b	e completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be complet	
<u>prior</u> to perf	orming maintenance activi	ties and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	: 11-8-22 Reason	n for Maintenance:	Rentin		,	
Property Address: 2	5820 23 ru St	No	Property Owner's I	Name: Etten a	unnoshau	
Municipality: Sty	Muchter zip:550	2 Property Ide	entification Numbe		01.00	
Maintenance Permit	No: <u>78459 629 18</u> 7	Maintainer Name	addiN B:	•		
/	2010140 110	Maintainer Name a	ild License No. Pin	ky's Environmental Se	wer Service/ L16	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped			Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintena			- All	11 25% of greater	
			enter authorization c	ode 100 016		
	ecurely replaced? Yes					
evidence of dam	of tank leakage from a sep	otic, holding, pret	reatment or pump	tank below the oper	ating depth or	
evidence of damaged, cracked, or structurally unsound maintenance hole covers?  Yes You						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
. How many gallons	of septage were removed?	?				
Tank #1 15 DD	gal Tank #2	gal Pretreatment	tankg	al Pump Tank	gal	
. Other information	: List any troubleshooting,	minor repairs cor	ducted, tank safe	ty concerns, or othe	r concerns	
	not	hing		, and a state of the state of t	concerns.	
		J	)			
. Location of septage	e disposal:	treatment	plant St. for			
	Pinky's	s Environmental Se	wer Service Inc.			
		PO Box 35	4			

Afton MN 55001

P: 651-439-4847 License Number: L1673