DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 0. 8319 U 25948

Date of Ma	intenance 3.10 A	eason for Maintenance:	merrially	ance con	noilla
Property A	ddress:961 SCO	artoit	Property Owner's Name: (phinda	Pic
Municipalit	FULLEST PORTS	State\\ Zip	Code 55 GEO	O Code/Property I.D. #:	<u> </u>
a aw	i (kv a sid o he (b)(hasvatim)		Marijemajishija	sopplie lenginon	
Tank(s) F	•	Liquid Level of	T-At :- at a		
Do tanks	nd scum measured. need to be pumped?	cidato cevelo	Taffk in. Slud	ge Level in. Scum L	evel in.
Yes	No (If no provide measure	ements) Total (Sludge 4	Scum) / Liquid	Level = %Sludge	& Scum
1. Access use	d to remove septage: - Ma	intenance Hole TiOth	er (Go to #3 helow)	* Tank must be pump	ed if this value
2. If maintena	ance hole was used, were all co	overs securely replaced?	ATYES TINO Please es	is greater than 25%.	, , , , , , , , , , , , , , , , , , , ,
Explanation	n:				
3. If owner re them comp	fuses to allow a Subsurface lete and sign the following :	Sewage Treatment Syst	tem (SSTS) to be pumped	through the maintenance	hole, have
I , ·					•
hole. I unde	rstand that removal of solids a	owner's name), reruse:	to allow the removal of so	lids and liquids through the	maintenance
4. Is the tank d	esigned as a leaky tank? exam	ple: seepaae nit. cessool	drivell leaching nit	idered maintenance,	
	Yes No Verificatio Meth				
		1 - 130	ioi		¥
	Yes No Verificatio Meth				•
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	ı:	
	Septic/Holding Tank #1	Yes No	Yes Alvo	Cover Damage	è
	Septic/Holding Tank #2	☐Yes ☐No	Yes No	Yes No	ē.
	Pretreatment Tank	Yes No	Yes No	Yes No	1
	Pump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many ga	ilions of septage were remov	ved?		Lites Lino	
Tank#1 135		Pretreatment Ta	7 61	mp Tank	
7. Other informa	ation: List any troubleshooti	ng, minor repairs condu	acted, tank safety concer	ns, or other concerns.	
8. Certification:	I hereby certify as a State of N and made the observations, c	Minnesota certified SSTS Nor directly supervised of the	Maintainer that I personally	conducted the work	
Maintainer's Na	nme: Olson's Sewer Service, I		•		
			r's Address: 17638 Lyons S	treet NE, Forest Lake, MN	
Maintainer's Lic		iner's Phone #: 651-464	-2082	ŧ	
Maintainer's Sig	nature M/K	6	Date: 3//	6/23	
	/		-		