## Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## **Subsurface Sewage Treatment System Maintenance Permit**

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance:	/-/-/ 6 Reason	for Maintenance:	Rea C	acot	
Property Address:	6336 Novell		Property Owner's Na	ame: Steve	aulson
Municipality:	ZIP: 55	Property Idea	ntification Number:		ŕ
1/4/12 7/17					
Maintenance Permit No: K940/n3615 Maintainer Name and License No. Smilie's Sewer Service/L2428					
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or great					25% or greater
1. Access used to rer	nove septage: Maintena	ince Hole 🗌 Other (e	enter authorization co	ode)	· .
2. Were all covers securely replaced? Ves $\square$ No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes 🗖 No	☐ Yes ☐ No	. ,
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	<b>i</b> ?			
Tank #1 / / / / gal Tank #2 gal Pretreatment tank gal Pump Tank					gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
<del></del>				1 (	
6. Location of septag	e disposal: <u>Mas</u>	4 60	Land ?	toply	<del></del>
	•	•			

Maintenance activities must be reported to the Department within 90 days.

