

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

11112 26CTION MINOST DE	completed in its entirety	to constitute a va	lid maintenance pe	ermit. This permit m	ust be completed	
prior to perfor	ming maintenance activit	ies and remain on	-site for the durati	on of the maintenance	e activity.	
Date of Maintenance:	Reason	for Maintenance: _	Key 1	lain T	5 /	
Property Address:	585 Paw	nee Avell	roperty Owner's Na	ame: Maria	bustrio	
Municipality: 57	Acateur ZIP: 550	Property Ide	ntification Number:			
Maintenance Permit N	· 10506:3617	<u> </u>		ie's Sewer Service/L2	 428	
	<u> </u>		2.1/8	TO A COMMON TO COMPANY OF THE PROPERTY OF THE		
/ Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to ren	nove septage: Maintena	ince Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers se	curely replaced? A res	□No				
3. Is there evidence	of tank leakage from a sepaged, cracked, or structur	ptic, holding, preti			iting depth or	
	· ·					
	Tank	Leaking Out	Leaking In	Cover Damage	/	
	Tank Septic/Holding Tank #1	Leaking Out	Leaking In Yes No	Cover Damage Ves No	/	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☐No	☐ Yes ☐No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		
* * * * *	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	
Tank #1/000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No Res No Res Res	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No		
Tank #1/000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Yes No Yes No Yes No Yes No Yes No Res No Res Res	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No		
Tank #1/000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No Yes No Yes No Res No Res Res	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No		
Tank #1/000	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	Yes No Yes No Yes No Yes No Yes No Res No Res Res	☐ Yes ☐ No ☐ tankg	☐ Yes ☐ No		