

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a	alid maintena		
This section must be completed in its entirety  prior to performing maintenance activiti	os and remain	and maintenance	permit. This permit	must be completed
prior to performing maintenance activiti	les and remain o	n-site for the dura	ation of the maintena	nce activity.
Date of Maintenance: 7-2/-/6 Reason	for Maintenance:	Rosani		
Property Address: 14844 mosgan M	re po	Property Owner's	Name: Pat K	earneu
Municipality: Marine ZIP: 550	Y Property Id	entification Numbe	r: **	9
Maintenance Permit No:01/9/14 12/07	aintainer Name	111		
Maintenance Permit No: CL6964 v 3/97 M	antamer Name a	and License No. Pir	nky's Environmental Se	ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
				f 25% or greater
1. Access used to remove septage:   Maintenance	e Hole Other	enter authorization o	code) /	VB
2. Were all covers securely replaced? $\square$ Yes $\square$	No		Veep 5	-7+6
<ol><li>Is there evidence of tank leakage from a septi evidence of damaged, cracked, or structural</li></ol>	ic holding prot	reatment or pump	tank below the oper	ating depth or
Tank	Leaking Out	Leaking In		
Septic/Holding Tank #1			Cover Damage	
	Yes No	Yes No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 /500 gal Tank #2	al Pretreatment	tankg	al Pump Tank	
5. Other information: List any troubleshooting, n	ninor repairs con	oducted tank safe	ty concerns	gal
		radeted, tallk sale	ty concerns, or other	concerns.
6. Location of septage disposal:	20			
	W/			

Maintenance activities must be reported to the Department within 90 days.