



## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	rmit. This permit m	iust be completed	
prior to perfor	ming maintenance activit	ies and remain on-	site for the duration	on of the maintenan	ce activity.	
Date of Maintenance:	8-9-16 Reason	for Maintenance:	Eutine		27	
Property Address: S	189 WK JUN	e Tyl. No. P	roperty Owner's Na	ime: Rul R	Meyer	
Municipality: ( )	Elma ZIP:55	U7Property Ider	tification Number:			
		and the same of th			wor Sanzica / 1673	
Maintenance Permit No	:V5989p3658M	Maintainer Name ar	d License No. Pilik	y s chiviloninientat se	wel service/E10/s	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks I	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage:   Maintena	nce Hole Other (e	enter authorization co	de)		
2. Were all covers see	curely replaced?  Yes	□ No				
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 / Soo gal Tank #2 gal Pretreatment tank gal Pump Tank					gal	
	: List any troubleshooting		nducted, tank safe	ty concerns, or othe	er concerns.	
Manho le	57 feet do	wn				
6. Location of septage	e disposal:					

Maintenance activities must be reported to the Department within 90 days.