

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety to	o constitute a val	id maintenance per	mit. This permit mus	st be completed
<u>prior</u> to perfor Date of Maintenance:	ming maintenance activitie	es and remain on or Maintenance:	site for the duration	or of the maintenance	activity.
Property Address: //	1660 62nd	TV P	roperty Owner's Na	me: Stoup 5	chuarte
(10)	water ZIP: 550			7	2.1.2.1
Municipality:	VASTO 22110		tification Number:		-
Maintenance Permit N	o: <u>XUSC15540</u> Ma	aintainer Name an	d License No. Smili	e's Sewer Service/L24	28
Maintena	nce Performed	Tank Meas	urement (must be o	completed if tanks NO	T pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: Maintenand	ce Hole 🗌 Other (e	nter authorization coo	de)	
2. Were all covers se	curely replaced? 🖊 es 🗆	□No			
3. Is there evidence	of tank leakage from a sept aged, cracked, or structura	ic, holding, pretr			ing depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes (No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?			7.	
Tank #1 / 250	gal Tank #2	gal Pretreatment	t tankga	l Pump Tank 500	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safet	y concerns, or other	concerns.
				1	
6. Location of septage	e disposal: Luas	h Co	Lano	1 Appl)