

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ety to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
prior to performing maintenance act  Date of Maintenance: 7-20-6 Reas	son for Maintenance:	7	on of the maintenand	ce activity.	
Property Address: 7925 180M	T// 1	roperty Owner's N	ame: Julie	Hall	
11	76.36			77011	
Municipality: // ZIP:5	505()Property Ider	ntification Number:		_	
Maintenance Permit No: <u>13737K335</u>	Maintainer Name an	d License No. Smi	lie's Sewer Service/L2	428	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped	Liquid Level of T	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measuremen	its) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maint	enance Hole $\Box$ Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? Ty	es 🗆 No				
3. Is there evidence of tank leakage from a evidence of damaged, cracked, or struc	septic, holding, pretr			ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes 🗖 No	☐ Yes ☐No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	$\square$ Yes $\square$ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo	ved?				
Tank #1 // gal Tank #2	gal Pretreatmen	t tank g	al Pump Tank	gal	
5. Other information: List any troubleshoot				r concerns.	
	/ 0		7		
6. Location of septage disposal:	34 (0	Land,	Tpply		