

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 7/19/16 Reason for Maintenance: Routine					
Property Address: 926 Manning Ave N Property Owner's Name: Bignarine LKS fore					
Municipality: Navive ZIP:55047 Property Identification Number:					
Maintenance Permit No: 14765 53343 Maintainer Name and License No. Smilie's Sewer Service/L2428					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see3. Is there evidence of	Maintenan curely replaced? Yes I of tank leakage from a sep ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump t	ank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes 🕅 No	☐ Yes ⊠No	
	Septic/Holding Tank #2	☐ Yes ⋈No	☐ Yes 🗚No	☐ Yes ⊠No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information	List any troubleshooting,	minor repairs co	nducted, tank safet	y concerns, or oth	er concerns.
6. Location of septage	disposal: P.B.C	W. Co.	1-A		