## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT 57510427413

Date of M	aintenance . 35	Reason for Maintenance	BROWNE	Minden
Property A	ddress: 9500 20	7th STN	Property Owner's Name:	Tim Buchi
Municipali	y: Forest Lake	State Zir	Code GE	4)4
w. Zaw	i (bysydaidau a sa		GE COL	O Code/Property I.D. #:
Tank(s)	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TO THE PERSON NAMED IN COLUMN T			ksomplite Plannish of pump of se
Sludge a Do tanks	and scum measured.  s need to be pumped?	Liquid Level o	3100	ge Level in. Scum Level in
Yes	No (If no provide measur		- unquita	Level = %Sludge & Scum
1. Access use	ed to remove septage: Min	aintenance Hole CiOtl	her (Go to #2 holows	
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain				
Explanation	n:			
3. If owner re them comp	fuses to allow a Subsurface lete and sign the following	Sewage Treatment Sys	tem (SSTS) to be pumped	f through the maintenance hole, have
1,				
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.				
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit				
	Yes Wo Verificatio Met		, arywen, reaching pit	
Tank#2	Yes No Verificatio Meth	nod Used:		
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?				
	Tank	Leaking Out	Leaking In	p.
	Septic/Holding Tank #1	Yes No		Cover Damage
	Septic/Holding Tank #2	☐Yes ☐No	Yes No	Yes No
	Pretreatment Tank	Yes No	Yes No	Yes No
	Pump Tank	Yes No	Yes No	Yes No
6. How many gallons of septage were removed?				
Tank #1 //7 Tank #2 Pretreatment Tank Pump Tank				
7. Other informa	tion: List any troubleshooti	ng, minor repairs condi	ucted, tank safety concern	ns, or other concerns.
8. Certification:	I hereby certify as a State of Mand made the observations, o	linnesota certified SSTS N	Maintainer that I personally	conducted the work
	me: Olson's Sewer Service, Ir	- only supervised of the	's Address: 17638 Lyons St	his job.
Maintainer's License #: 216 Maintainer's Phone #: 651-464-2082				
Maintainer's Sig	nature	m	Date: 4	-25-17
	// "	//		