

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ety to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
prior to performing maintenance act	ivities and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance: 7-7-6 Rea	son for Maintenance:	Pea M	9051		
11180 175	4 711		1-1	Maladaci	
Property Address: 6 4 0 1 2 1	7 / / P	roperty Owner's N	ame: / Um /	Telan Con	
Municipality: / ZIP:	5// OProperty Ider	ntification Number:			
Maintenance Permit No: 472935352	Maintainer Name an	d License No. Smi	lie's Sewer Service/L2	1428	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of T	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurement	nts) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
Were all covers securely replaced?  3. Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.  Tank	septic, holding, pretr			ating depth or	
Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes 🗖 No	☐ Yes ☐No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remo	oved?				
Tank #1 / 250gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshoo				r concerns.	
			1		
6. Location of septage disposal:	-//		24		