DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 198749 27617

Date of Maintenance 5-4-23	Reason for Maintenance:) complian	,	ľ
Property Address: 23780 A	Flay Allew	Property Owner's Name:	Deb Brown	
Municipality: Forest Lohe	State Zip	Code G	EO Code/Property I.D. #:	_
aWhat was done to the system.				_
Tank(s) Pumped		And the Colon of the Line of	acomplete of Armiconol pounds of a	
Sludge and scum measured. Do tanks need to be pumped?	Liquid Level o	3100	ige Level in. Scum Level	in
Yes No (If no provide measur			Level = %Sludge & Scum	
1. Access used to remove septage: AMM	intenance Hole Otl	ier (Go to #3 below)	* Tank must be pumped if this va	due
2. If maintenance hole was used, were all of Explanation:	overs securely replaced?	Yes No please e	is greater than 25%. Xplain	
If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Sys statement:	tem (SSTS) to be pumpe	d through the maintenance hole, have	2
l, :	(OWner's name) refere	An - 11		
hole. I understand that removal of solids a	and liquids through other	to allow the removal of so	olids and liquids through the maintenance	:e
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool	dowell leaching nit	sidered maintenance.	
Tank#1 Yes No Verificatio Meth		arywen, leaching pit		
Tank#2 Yes No Verificatio Meth	4 ———			_
The Actividatio Meth				
5. is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	low the operating depth or evidence of	of
Tank	Leaking Out	Leaking In		
Septic/Holding Tank #1	☐ Yes ☑ No		Cover Damage	
Septic/Holding Tank #2	☐Yes ☐No	Yes No	Yes ANO	
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remove	/ed?	D is Mile	Yes No	
Tank#1 1250 Tank#2	Pretreatment Ta		mp Tank (Sch.)	
7. Other information: List any troubleshooting	ng, minor repairs condi	icted, tank safety conce	700	
_ tank 1 Bottom c	rached	the state of the s	113, Of Other Concerns.	
B. Certification: I hereby certify as a State of M and made the observations, o	linnerota continua cere a	Maintainer that I personally	y conducted the work	
Maintainer's Name: Olson's Sewer Service, In		's Address: 17638 Lyons S		
Maintainer's License #: 216 Maintai	ner's Phone #: 651-464		, orest take, MIN	
Maintainer's Signature	Lynn.	Date: 5	4-23	