

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perfor	ming maintenance activitie	s and remain on	site for the duratio	n of the maintena	nce activity.
Date of Maintenance:	7/18/16 Reason fo	or Maintenance: _	Reg.	maint	
Property Address: 5	580 Chestaut	- St. P	roperty Owner's Nar	ne: Low	Pardun
Municipality: ZIP: SSCH7 Property Identification Number:					
Maintenance Permit No: XL&2L7_3338 Maintainer Name and License No. 5milie' - 5438					
Maintenar	nce Performed	Tank Meas	urement (must be c	ompleted if tanks	NOT pumped)
🖟 Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage: Maintenance Hole Other (enter authorization code)</li> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes X No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes X No	☐ Yes XNo	☐ Yes \\\	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	• j
4. How many gallons of septage were removed?					
Tank #1 1006	gal Tank #2 100c	gal Pretreatmen	tankgal	Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safety	y concerns, or oth	er concerns.