

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Ma	intenance <u>5-1/-23</u> Re	eason for Maintenance:			^
	idress: 23230 57 (steve Behrens	_
Municipality	· scardia	_		EO Code/Property I.D. #:	_
W. Wi	ativvasidone lozine syriem?		TAXABETES YET WAS INCOME.		
Tank(s) P	umped			e complete la la companion de	
Sludge and scum measured.		Liquid Level o	f Tarik in. Slu	dge Level in. Scum Level	in
Do tanks need to be pumped? Description of the provide measurements of the pumped.		Total (Studen	15000	The same of the sa	
	No (If no provide measures			i Level = % Sludge & Scum	
1. Access used	to remove septage: Mai	ntenance Hole Oth	ier (Go to #3 below)	* Tank must be pumped if this va	line
2. If maintenal	nce hole was used, were all co	vers securely replaced?	Fives Fible places	is greater than 25%.	IUC
Explanation	:		I no piease e	xpiain	
3. If owner ref	uses to allow a Subsurface S	ewage Treatment Sys	tem (SSTS) to be pumpe	d through the maintenance hole, have	-
	ete and sign the following st	atement:	95	a through the maintenance hole, have	ŧ
l,		(owner's name), refuse	to allow the removal of so	olids and liquids through the maintenance	
noie. Tunder			ALLESE DUIDAG IS WAY """	sidered maintenance	e
	as a leaky tank! examp	ie: seepage pit, cesspool	drywell, leaching pit		
Tank#1 🔲 Y	es No Verificatio Metho	d Used:			
Tank#2 Y	es No Verificatio Metho	d Head:			
5. is there evide	ince of tank leakage from a	and a day			
5. is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	r.	
	Septic/Holding Tank #1	Yes No	Yes No	Cover Damage	
	Septic/Holding Tank #2	Yes No	Yes No	Yes No	
	Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No	
	Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	
6. How many gall	ons of septage were remove	d?		Lites LINO	
Tank#1 ///	O Tank#2 1000	Pretreatment Ta		mp Tank	
7. Other informat	ion: List any troubleshooting	, minor repairs condu	ıcted, tank safety concei	rns, or other concerns.	
a : Certification: i	hereby certify as a State of Mir nd made the observations, or	nesota certified SSTS N	laintainer that I personall	y conducted the work	
	, , ,	an early supervised of the	ers in the performance of	this job.	
	ne: Olson's Sewer Service, Inc.	Maintainer	's Address: 17638 Lyons S	treet NE, Forest Lake, MN	
Maintainer's Lice	nse #: 216 Maintain	r's Phone #: 651-464-			
Maintainer's Sign					
	And His	-	Date: 3	11-25	
	91				