

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety t	o constitute a va	lid maintenance pe	ermit. This permit mu	ist be completed
prior to performing maintenance activities	es and remain on	-site for the durati	on of the maintenanc	e activity.
Date of Maintenance: $7 - 14 - 16$ Reason f	or Maintenance: _	Cleaning		
Property Address: 5638 Julep Way	F	Property Owner's N	ame: Wade Fi	ck
Municipality: Lake Elmo ZIP: 5504				
Maintenance Permit No: <u>n 407763335</u> Ma				428
Maintenance Performed	Tank Meas	urement (must be	completed if tanks No	OT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage: Maintenance</li> <li>Were all covers securely replaced? Yes</li> </ol>		enter authorization co	ode)	
20-9- Carbon-Maria Souther 1930-Chebratica (Medicarda) (Medicarda) (Medicarda) - Carbon - Car			4	tion double on
<ol><li>Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura</li></ol>				ting depth of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ੴNo	☐ Yes 🖾 No	☐ Yes ☐No	
Septic/Holding Tank #2	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ੴNo	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 1,000 gal Tank #2 1,000	gal Pretreatmen	t tank g	al Pump Tank 300	gal
5. Other information: List any troubleshooting,				
11/4				
6. Location of septage disposal:				<del></del>