DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT HO203B29770

Date of Maintenance 5/12/23	Reason for Maintenance	re:	ON 11070207 1 1/(
Property Address: 19930 Harr			
Municipality: Forest Lake		rroperty Owner's Name	e: William Salverda
	state 40	Cip Code 55025	GEO Code/Property I.D. #:
Tank(s) Pumped	5 to 10	haviriyo de je slavio	e sampling like nemogram states.
Sludge and soum measured	Liquid Leve	1-6- A	
Do tanks need to be pumped? Yes No If no provide many	Total (Ct		in. Scum Level in.
The arms provide measu	rements) Total (Sludge		id Level = %Sludge & Scum
1. Access used to remove septage: M	laintenance Hole 📈 O	ther (Go to #3 below)	
2. If maintenance hole was used, were all of	covers securely replaced	1? Tives Tible	is greater than 25%.
exhibition;			
3. If owner refuses to allow a Subsurface them complete and sign the following	Sewage Treatment Su	chara (COMA)	
them complete and sign the following	statement:	stem (SSTS) to be pump	ed through the maintenance hole, have
·, ·	/a		
hole. I understand that removal of solids 4. Is the tank designed as a leaky tank? exam	and liquids through oth	e to allow the removal of s	colids and liquids through the maintenance
4. Is the tank designed as a leaky tank? exam	iple: seepage nit cessage	er access points is not con	sidered maintenance.
Tank#1 Yes No Verificatio Met	nod Used:	n, urywell, leaching pit	
Tank#2 ☐ Yes ☐ No Verificatio Meth			
5. Is there evidence of tank looking a	od Used:		
5. Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	septic, holding, pretre	atment or pump tank be	elow the operating dames and an arrival
Tank	Leaking Out	ı	I .
Septic/Holding Tank #1	Yes No	Leaking In	Cover Damage
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No
Pump Tank	Tyes TNo	Yes No	☐Yes ☐No
6. How many gallons of septage were remov	ed?	☐ Yes ☐ No	☐ Yes ☐ No
Tank#1 700 Tank#2			
	Pretreatment Ta	nk Pui	mp Tank
7. Other information: List any troubleshootin	g, minor repairs condu	icted, tank safety concer	ns, or other concerns
8. Certification: I harabu and			contents.
8. Certification: I hereby certify as a State of Mi and made the observations, or Maintainer's Names of the control of the con	nnesota certified SSTS N	laintainer that I personally	Conducted the west
Maintainer's Name: Olson's Sewer Service, Inc		and benoutifuling of £	nis job.
	. Maintainer	s Address: 17638 Lyons S	treet NE, Forest lake MAN
Maintainer's License #: 216 Maintain	er's Phone #: 651-464-		
Maintainer's Signature		1	
	1.1	Date: 5/	2/23
*		-	