

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	,	to constitute a vai	id maintenance pe	ermit. This permit mu	ist be completed
<u>prior</u> to perfori	ming maintenance activiti	es and remain on-	site for the dyrati	on of the maintenance	e activity.
Date of Maintenance: 7	7-14-16 Reason	for Maintenance:	Ken Ma	ach T	
, ~		1 111		11/10	C. E
Property Address: / <	Upu segu	Aug Tr/M	roperty Owner's Na	ame: VIm Pe	nit -
Municipality: SCOO	relia ZIP:550	Property Ider	ntification Number:		_/
Maintenance Permit No	V 1508 13118 N	 Naintainer Name an	d License No. Smil	lie's Sewer Service/L2	428
Maintenance remine no	· <u> </u>				
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers see	curely replaced? Yes	□No			
3. Is there evidence of	of tank leakage from a sep ged, cracked, or structur	tic, holding, pretr	eatment or pump tenance hole cove	tank below the opera ers?	iting depth or
	Tank	Leaking Out	Leaking lņ	Cover Damage	
	Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No	
	Pro-Maria Salaria	1/			
	Septic/Holding Tank #1	☐ Yes ♠No	☐ Yes ☐No	☐ Yes ☐No	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐No☐ Yes ☐No	☐ Yes ☐No☐ Yes ☐No	☐ Yes ☐ No	
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	
AND THE RESIDENCE AND ADDRESS OF THE PARTY O	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Yes No Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	O gal
Tank #1 />50	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ Ro gal Pretreatmen	 ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No 	☐ Yes ☐ No	gal r concerns.
Tank #1 />50	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ Ro gal Pretreatmen	 ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No 	☐ Yes ☐ No	gal r concerns.
Tank #1 />50	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ Ro gal Pretreatmen	 ☐ Yes ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No 	☐ Yes ☐ No	gal r concerns.