

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	id maintenance pe	ermit. This permit m	ust be completed	
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	site for the durati	on of the maintenance	e activity.	
Date of Maintenance:	7-19-16 Reason	for Maintenance:	Kea	Massit		
		, ,-	1	+ 6	1	
Property Address: 2	22 Lunsdale	Ave N	roperty Owner's Na	ame: Vac	rayzwa	
Municipality: Lake	Elno ZIP:550	42 Property Idea	ntification Number:			
	1405150111					
Maintenance Permit No	: m (10CD) 11	Maintainer Name ar	d License No. Smi	lie's Sewer Service/L2	428	
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced?	otic, holding, pretr			ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes 🗷 No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
-175-2	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4 How many gallons	of sentage were removed					
4. How many gallons of septage were removed? Tank #1 gal Tank #2 gal Pretreatment tank				al Pump Tank	gal	
	: List any troubleshooting				r concerns.	
5. Other information	. List any troubleshooting	s, minor repairs co	naactea, tank sare	ity conderns, or con-		
				1 (15)	,	
6. Location of septage	e disposal: Was	4 Co	Land	Appl		