1960/2/4783

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

| Date of M | aintenance <u>05/25/23</u> | Reason for Maintenance | | | |
|--|---|---|------------------------------------|---|--------------|
| Property A | ddress: 15901 PUT | NAM BLUD | Property Owner's Name: | | |
| Municipali | AFTON | State MN Zi | • | EO Code/Property I.D. #: | |
| | la (was cone to the continu | 建 | | i Dispublication de la comme | Sources |
| Tank(s)! | Pumped | Liquid Level | 6 - A | | PHIL |
| Do tanks | and scum measured. I need to be pumped? | Lidaia FeAS! | in. Sludge Level in. Scum Level in | | |
| Yes | No (If no provide measur | ements) Total (Sludge | + Scum) / Liquid | d Level = % Sludge & Se | Pilm |
| 1. Access use | d to remove septage: (EM | | hor (Co eo 42 to to | | - |
| 2. If maintena | ance hole was used, were all c | overs securely replaced: | Yes Finoplease | * Tank must be pumped in is greater than 25%. | f this value |
| Explanation | n: | | \ | | |
| 3. If owner re | fuses to allow a Subsurface lete and sign the following | Sewage Treatment Sys | item (SSTS) to be pumpe | ed through the maintenance ho | |
| l | iete and sign the following | | 652 | | |
| hole. Lunde | retand that removed of the | (owner's name), refuse | to allow the removal of s | olids and liquids through the mai | ntonanca |
| 4. Is the tank de | rstand that removal of solids a | | | sidered maintenance. | renance |
| the second second | esigned as a leaky tank? exam | | l, drywell, leaching pit | | |
| Janka I | Yes No Verificatio Meth | ood Used: | | | |
| Tank#2 | | od Used: | | | |
| Is there evidence damaged, cra | ence of tank leakage from a acked, or structurally unsou | septic, holding, pretre | atment or pump tank be | elow the operating depth or evi | dence of |
| | Tank | Leaking Out | Leaking In | 1 | |
| | Septic/Holding Tank #1 | ☐Yes ☑No | Yes No | Cover Damage | |
| | Septic/Holding Tank #2 | Yes No | Yes No | Yes ONo | |
| | Pretreatment Tank | ☐Yes ☐No | Yes No | Yes No | |
| | Pump Tank | Yes No | Yes No | Yes No | |
| 6. How many gal | lions of septage were remov | red? | | 1100 | |
| Tank#1 | 7 Tank #2 1250 | Pretreatment Ta | | mp Tank 400 | |
| 7. Other information | tion: List any troubleshootir | g, minor repairs condu | icted, tank safety conce | rns, or other concerns. | |
| 8. Certification: | hereby certify as a State of M | in | | | |
| ě | hereby certify as a State of Mand made the observations, or | mnesota certified SSTS N directly supervised other | Maintainer that I personally | y conducted the work | |
| Maintainer's Nar | me: Olson's Sewer Service, In | | 's Address: 17638 Lyons S | | |
| Maintainer's Lice | ense #: 216 Maintair | ner's Phone #: 651-464- | | , orest rave' Wild | |
| Maintainer's Sigr | | 031-104 | | en e | |
| canter s sign | isture Jes Ma | h | Date: 5- | 15 5 23 | |
| | | | | | |