DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 604502992

Date of Mainte	enance 5 31 23 R	leason for Maintenance:		,	
Property Addre	7 7	-th st N	Property Owner's Name:	Adam Gs	ahek
Municipality:	Scandia	State MW Zip	Code 55073 GI	EO Code/Property I.D. #:	nger
	vas done lozhesy tem.		Note: The same of the same	(देखकोचेदर मिश्च त्रास्त्राह्म इ.स.च्या	
Tank(s) Pum				2040 November of the Control	Dimberi
Sludge and scum measured.		Liquid Level o	Tarik in. Sluc	ige Level in. Scurr	Level in
	ed to be pumped?	Total (Sludge	Scum) / Liquic		
	No (If no provide measure	emens)			e & Scum
1. Access used to	remove septage: Ma	intenance Hole Oth	er (Go to #3 below)	* Tank must be pur	nped if this value
Z. If maintenance	hole was used, were all co	overs securely replaced?	Yes No please	is greater than 250 explain	%.
Explanation:			<i>[</i>		
3. If owner refuse	es to allow a Subsurface and sign the following :	Sewage Treatment Syst	tem (SSTS) to be pumpe	d through the maintenan	rehole have
l.	e and sign the following :				
	and that removed of a list	(owner's name), refuse	to allow the removal of s	olids and liquids through th	e maintenance
4. Is the tank design	and that removal of solids	and udains tutoridu othe	l access points is not con	sidered maintenance.	
	ned as a leaky tank? exam		drywell, leaching pit		
Tank#1 Yes	No Verificatio Meth	od Used:			
Tank#2 Yes	☐ No Verificatio Meth	od Used:			
5. Is there evidence damaged, crack	e of tank leakage from a ed, or structurally unsou	sentic halding protect	atment or pump tank be	elow the operating depth	or evidence of
	Tank	Leaking Out	1		•
3	Septic/Holding Tank #1	Yes No	Yes No	Cover Damage	_
S	eptic/Holding Tank #2	☐Yes ☐No	Yes No	Yes No	
P	retreatment Tank	Yes No	Yes No	Yes No	-ş
P	ump Tank	Yes No	☐ Yes ☑ No	Yes No	-
6. How many gallor	ns of septage were remov	/ed?	70	Lifes David	-
Tank#1 1500	Tank #2	Pretreatment Ta	nk Pu	Imp Tank 400	
7. Other informatio	n: List any troubleshooti	ng, minor repairs condu	icted, tank safety conce	the orothoron	
				or other concerns.	
8. Certification: The	ereby certify as a State of M I made the observations, o	linnesota certified SSTS N	laintainer that I personal	ly conducted the work	
	: Olson's Sewer Service, Ir				
would a thouse	- Olson's Sewer Service, ir	Maintainer	's Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's Licens	e #: 216 Maintai	ner's Phone #: 651-464	-2082		
Maintainer's Signat	ure / *	∇	Dec gar		
	10	-	Date: 5	31/23	