

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	completed in its entirety	to constitute a val	d maintenance pe	ermit. This permit m	ust be completed	
prior to perform	ning maintenance activit	ies and remain on-	site for the durati	ion of the maintenance	ce activity.	
Date of Maintenance:	7-06-16 Reason	for Maintenance:	Youtine	ell ainte	nance	
Property Address: 13	31dp 50th St	, Alton P		ame: Terry	<u> Viegele</u>	
Municipality:	ZIP:550	Property Iden	tification Number:			
Maintenance Permit No	: <u>e4855m3300</u> 1	Maintainer Name an	d License No. Ron'	s Sewer Service/ L210	3	
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to b		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or great					
2. Were all covers sec 3. Is there evidence of	nove septage: A Maintena curely replaced? Yes of tank leakage from a sep ged, cracked, or structur	□ No ptic, holding, pretr	eatment or pump	tank below the opera	ating depth or	
0,100,100	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ∰No	☐ Yes TNo	☐ Yes ♣ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	d?				
Tank #1 /250 gal Tank #2			t tank§	gal Pump Tank	gal	
5. Other information	: List any troubleshooting	— g, minor repairs co	nducted, tank saf	ety concerns, or othe	r concerns.	
	, i					
	38					
6. Location of septage	e disposal:					