Q4054X29776 DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 6/1/23	Reason for Maintenance:			
Property Address: 14320 Hyde	e Ave	Property Owner's Name:	MAMANDA POSANOU	iski
Hugo	State Au Zig	Code 55038 G	EO Code/Property I.D. #:	
What was done to the sy tem.	t, jan	Mertinomentalining	Gsombler Herbitanov - s	Selenovie.
Tank(s) Pumped	l iquid tour!	er de		
Sludge and scum measured. Do tanks need to be pumped?	Liquid Level o	in. Sluc	ige Level in. Scum Level	iı
Yes No (If no provide measure	Total (Sludge	+ Scum) / Liquic	llevel - ever	
יוט פון אוייט פון אייט פון אוייט פון אוייט פון אייט	emens			
1. Access used to remove septage: Ma	aintenance Hole []Ot	ner (Go to #3 below)	* Tank must be pumped if	this valu
2. If maintenance hole was used, were all co	overs securely replaced?	Yes No please	is greater than 25%. Explain	
Explanation:				
3. If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Sys	tem (SSTS) to be pumpe	d through the maintenance hold	
l, ·		,		
hole. I understand that removal of solids	(owner's name), refuse	to allow the removal of so	olids and liquids through the main	enance
hole. I understand that removal of solids a 4. Is the tank designed as a leaky tank? exam			sidered maintenance.	CHENCE
the Aura time		arywell, leaching pit		
Tank#1 Yes No Verificatio Meth	nod Used: Vest	eal		
Tank#2 Yes No Verificatio Meth	od Used: Visu	226		-
Is there evidence of tank leakage from a damaged, cracked, or structurally unsou	contic halding		low the operating dones	
Tank	1	1	- Farama debtil of GAIG	≥nce of
Septic/Holding Tank#1	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #2	Yes No	Yes ANO	☐ Yes ∰No	
Pretreatment Tank	Yes No	Yes No	☐ Yes ☑No	
Pump Tank	Yes No	Yes No	Yes No	
6. How many gallons of septage were remov	Yes HNo	Yes DiNo	Yes No	
	rear			
1000	Pretreatment Ta		mp Tank 200	
7. Other information: List any troubleshooting	ng, minor repairs condu	icted, tank safety concei	ns, or other concerns.	
8. Certification: I hereby certify as a State of M and made the observations, o	linnesota certified SSTS N	laintainer that I personall	y conducted the work	
	and a control of the control of the	ers in the performance of	this job.	
Maintainer's Name: Olson's Sewer Service, In	nc. Maintainer	's Address: 17638 Lyons S	treet NE, Forest Lake, MN	
Maintainer's License #: 216 Maintain	ner's Phone #: 651-464		1	_
Maintainer's Signature			<i>(</i>)	
The state of the s)	Date: 6/	1/23	
<i></i>		,		